



Canadian Standards Association
Mississauga, Ontario
To the Part I Committee

Subject No. 2897-38

Chair: D. McColl

Date: December 2, 2003

Title: Request for an Interpretation, Rule 38-036(3)

Submitted by: Shawn Paulsen of NB Dept. of Labour, P.O. Box 6000, Fredericton, New Brunswick, Tel: (506) 453-2336, Fax: (506) 457-7394 on October 25, 1999.

Proposal: Request for an official interpretation in Section 38 dealing with elevators.

In CEC Rule 38-036(3), we are including *elevating devices for the handicap* or *handicap lift* as a *hydraulic elevator* in which case an auxiliary contact must be installed in the disconnecting means to open the emergency power to the control circuit. Is this correct?

Chair's Proposal: Close Subject 2897-38.

Rationale: This subject was addressed by the Section 0 Committee in Subject 2897-0. The concerns raised in the Interpretation Request were also resolved in the rewrite of Section 38 (Subj 2566) and are no longer applicable in the 19th Edition (2002).

Subcommittee Deliberation: The Section 38 Chair's proposal to close this subject for the reasons shown in the Rationale was approved unanimously by the Section 38 members who responded.

Subcommittee Recommendation: To close the subject.